



SANDIA aerospace
3700 Osuna Rd NE. Ste 711
Albuquerque, NM 87109
505.341.2930

SERVICE BULLETIN

Number 112
March 16, 2021

ACF 328 Reliability Improvement

Effectivity

Model ACF 328 S/N 19000 and above

Purpose

To prevent failure of the fan circuit card during over voltage and voltage spike conditions

Compliance

As required on existing installed ACF 328 cooling fans

Approval

Does not affect Approvals

Manpower

30 minutes for removal and reinstallation

Modification Procedures

Return unit(s) to Sandia Aerospace for modification and functional performance verification.

Markings

Mark Rev 4 on ACF 328 identification tag